






EMS PERFORMANCE REPORT

TELEMARK SKI CLUB LODGE
RESORT CLUB LODGES (BED NUMBERS < 19)

EXECUTIVE SUMMARY

1 MARCH 2021 - 28 FEBRUARY 2022

QUANTITATIVE INDICATORS



QUALITATIVE INDICATORS

✘ Below the target ✔ Meets the target ★ Exceeds the target N/A Not Applicable

No individual figures are collected against this target. Total waste figures for the PRR will be included in the combined annual report.

The achievement of this target is collectively assessed in the 'All Lodge' report.

- Question not implemented in software.

	Target	2011/2012	2012/2013	2013/2014	2014/2015	2015/2016	2016/2017	2017/2018	2018/2019	2019/2020	2020/2021	2021/2022
1	100% lodges have thermostat settings	-	-	-	-	-	-	-	-	-	✔	✔
2	100% lodges have timer systems and/or sensor switches for lighting and heating	-	-	-	-	-	-	-	-	-	✔	✘
3	100% lodges use off-peak hot water or instantaneous gas hot water	-	-	-	-	-	-	-	-	-	✔	✔
4	25 % lodges purchase green power from your electricity provider	-	-	-	-	-	-	-	-	-	✘	✘
5	100 % lodges have more than 75% of your light bulbs fluorescent, LED, or high efficiency/long life light bulbs	-	-	-	-	-	-	-	-	-	✔	✔
6	100 % lodges provide signs or other measures to encourage guests, visitors and staff to minimise energy use	-	-	-	-	-	-	-	-	-	✔	✔
7	100 % lodges separate out food waste and dispose of it through the composting waste stream	-	-	-	-	-	-	-	-	-	✔	✔
8	Zero pollution incidents.	✔	✔	✔	✔	✔	✔	✔	✔	✔	✔	✔
9	Less than 10% of lodges using open fireplaces as their primary source of heating.	-	✔	✔	✔	✔	✘	✘	✘	✔	✔	✔
10	More than 90% of lodges implementing water saving measures.	-	✔	✔	✔	✔	✔	✔	✔	✔	✔	✔
11	Lodges only using local native plants for landscaping.	-	✔	✔	✔	✔	✔	✔	✘	✘	N/A	N/A
12	All lodges located in high priority areas on the Perisher Rehabilitation Plan to have rehab plans developed for their lease.	-	N/A	✘	✘	✘	✘	✘	✘	✘	N/A	N/A

13	No lodges using baits, snares, traps or rat poison as pest control without NPWS approval.	-	✓	✗	✗	✗	✓	✓	✓	✓	N/A	N/A
14	60% of lodges undertaking weed control	-	✗	✗	✗	✗	✗	✗	✗	✗	✓	✓
15	100% hydrocarbon storage containers compliant and managed appropriately.	✓	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A
16	All redundant hydrocarbon fuel storage tanks decommissioned and sites validated.	✓	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A
17	100% of significant incidents reported to NPWS.	-	✓	✓	N/A	N/A	N/A	N/A	-	-	-	-
18	100% incidents managed in a timely manner.	-	✓	✓	N/A	N/A	N/A	N/A	-	-	-	-
19	100% of lodges who store chemicals/fuel to have well equipped spill kits.	✓	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A
20	100% of lodges who store chemicals/fuel clearly displaying PRREMS Lodge Incident Procedure.	✓	✗	✓	✓	✓	✓	✓	✓	✓	N/A	N/A
21	100% of grease traps working effectively	✓	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A
22	To reduce amount of CO2 equivalent emitted per visitor night.	✗	★	★	✗	★	✗	✗	✗	★	N/A	N/A
23	Less than 20% of lodges using ODS appliances.	-	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A
24	To reduce amount of waste produced	#	#	#	#	#	#	#	#	#	#	#
25	100% of lodges recycling.	-	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A
26	To recycle more than 50% of total waste.	✓	★	★	★	★	★	★	★	★	N/A	N/A
27	Energy use per visitor night to be better than PRREMS lodge sector average (based on 2018 benchmarking report).	✗	✗	✗	★	✗	✗	✗	★	★	-	-
28	More than 5% of total energy used to come from renewable sources.	✗	✗	✗	✗	✗	✗	✗	✗	✗	N/A	N/A
29	Less than 200L of water used per visitor night.	★	★	★	★	★	★	★	★	★	N/A	N/A
30	100% of lodges regularly inspecting their lease for erosion	-	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A

problems												
31	100% of lodges with erosion issues taking actions to prevent and manage the erosion.	-	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
32	75% of lodges educating guests and staff about PRR cultural heritage values.	-	✓	✗	✗	✗	✓	✓	✓	✓	N/A	N/A
33	100% lodges have lease areas free from excess building materials, equipment, garbage, weeds and other items that negatively affect scenic value.	-	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A
34	100% of staff EMS awareness trained.	-	✓	✓	✓	✓	N/A	N/A	N/A	N/A	N/A	N/A
35	100% of organisations with fully implemented EMS's for their operations within Perisher Range Resorts.	##	##	##	##	##	##	##	##	##	##	##
36	100% of lodge committees annually review and discuss their environmental risks.	-	✓	✓	✓	✓	✓	✓	✓	✓	N/A	N/A

Additional Information

Weed control
Weed monitoring and removal as needed in place as per area plan

Incidents or Spills
No Comment Provided

Other Comments
Awareness sessions, signage regarding water conservation, dual flush, flow restrictions. .
